







TECHNICAL BULLETIN TECH-03-2021

VW 2.0L - 830324-5004S TURBOCHARGER REPLACEMENT

12TH MARCH 2021



www.garrettmotion.com MAR. 12, 21



VW 2.0L - 830324-5004S TURBOCHARGER REPLACEMENT

Dear Customer,

Please note, that production of turbocharger 04L 253 020 G / 830324-5004S was stopped.

As a replacement is available turbocharger 04L 253 014 H / 873732-5001S, which <u>is not a direct service replacement</u> for 830324-5004S.

• There is a different position of the flange for EGR pipe on turbine housing – see below



To replace turbocharger 830324-5004S to be ordered following:

- o From Garrett Turbocharger 873732-5001S
- o From franchised VW dealer
 - EGR pipe
 - Gaskets
 - Heatshield
 - Necessary fasteners








www.garrettmotion.com MAR. 12, 22



VW 2.0L - 830324-5004S TURBOCHARGER REPLACEMENT

Parts to be ordered from franchised VW dealer

- o EGR pipe
- Gaskets
- Heatshield
- Necessary fasteners



Please distribute this information to all in your company who may need it.

Best Regards, Arnošt Pátík IAM Senior Technical support Specialist Garrett – Advancing Motion







www.garrettmotion.com MAR. 12, 21